


CASON
EVR125
1987
S57
C.2

ISBN 0-7729-2597-6

SNOW SAMPLING SURVEY
in the vicinity of
DOMTAR PACKAGING LIMITED
RED ROCK, ONTARIO, 1986.



Ministry
of the
Environment

W.M. Vrooman
Regional Director
Northwestern Region

Copyright Provisions and Restrictions on Copying:

This Ontario Ministry of the Environment work is protected by Crown copyright (unless otherwise indicated), which is held by the Queen's Printer for Ontario. It may be reproduced for non-commercial purposes if credit is given and Crown copyright is acknowledged.

It may not be reproduced, in all or in part, for any commercial purpose except under a licence from the Queen's Printer for Ontario.

For information on reproducing Government of Ontario works, please contact ServiceOntario Publications at copyright@ontario.ca

CASON
EUR 125
1987
S57
C.2

ISBN 0-7729-2597-6

SNOW SAMPLING SURVEY
in the vicinity of
DOMTAR PACKAGING LIMITED
RED ROCK, ONTARIO
1986

D. J. Racette
Environmental Scientist
H. D. Griffin
Chief, Air Quality Assessment

TECHNICAL SUPPORT SECTION
NORTHWESTERN REGION
ONTARIO MINISTRY OF THE ENVIRONMENT
June, 1987

Gift: Ministry of the Environment

INTRODUCTION

Domtar Packaging Limited operates a kraft pulp mill in the town of Red Rock. Ministry of the Environment studies in 1977 and 1978 revealed that sodium and sulphate, discharged to the air from the mill, were significantly elevated in snow in the surrounding area.^{1,2}

In October 1982, Domtar installed a new recovery boiler. Moss exposure studies in 1983-84 showed much reduced levels of sodium as a result of this abatement action.³

To determine the current status of particulate fallout in Red Rock, a snow sampling survey was conducted in February, 1986.

METHODS

Single samples of snow were collected on February 14, 1986 from 11 sites near the Domtar kraft mill (Figure 1) and from two control sites remote from the study area. Core samples of the complete snow profile were obtained following standard Ministry sampling procedures.⁴ Snow meltwater samples were submitted to the Ministry's Thunder Bay Laboratory for determination of calcium, sodium, chloride, sulphate, conductivity and pH. Analysis of carbon and solids was performed at the Ministry's Toronto Laboratory.

Contaminant guidelines developed by the Ministry are used in this report. Their exceedence would suggest that contamination may be present, but would not necessarily imply adverse effects.

Insoluble particulate matter in selected samples of snow meltwater were examined with a dissecting microscope.

RESULTS

Chemical analysis results from the 1978 and 1986 surveys are presented in Tables 1 and 2. Levels of some parameters slightly exceeded Ministry guidelines at sampling sites off company property. The distribution patterns for all parameters were similar to one shown in Figure 2 for suspended solids. Parameter values were highest near the mill and declined as distance from the mill increased.

Except for sulphate, which declined from 1978 to 1986, snow chemistry in 1978 and 1986 was similar (Table 1).

Sample core depth of snow averaged 38 cm (centimetres) and ranged from 30 to 48 cm. Trace to moderate quantities of wood fines and black particulate matter (wood or bark char) were visible in the snow profile or on the snow surface at all sites, except at stations 18, 25 and at the two controls. Heaviest concentrations of wood fines were found near the mill and woodchip piles, while black particulate matter was distributed uniformly at most sites. Microscopic examination determined that, at sites on company property, wood fibres and wood and bark char accounted for about 90% of the suspended solids in snow. In the townsite, these substances also comprised most of the suspended solids, but suspended solids values met the Ministry guideline in the townsite area.

CONCLUSIONS

The 1986 snow survey around Domtar Packaging Limited in Red Rock demonstrated that snow chemistry usually met Ministry guidelines at off-property sampling sites. The few guideline exceedences off property were not excessive. Levels of calcium, chloride, sodium and pH were similar to values reported for a previous survey in 1978.

Sulphate concentrations were lower in 1986 than in 1978. Significantly elevated concentrations of all parameters were restricted to company property. Levels of particulate fallout, as determined by this study, pose no known potential nuisance or environmental hazard. These results confirm findings from the Ministry's dustfall measurement program in Red Rock, which shows that, off company property, fallout of particulate matter usually complies with Ontario objectives.⁵ Beyond the current Control Order issued to Domtar Packaging Limited, which includes controls on air emissions, results of the 1986 snow sampling survey do not indicate a need for further abatement of particulate matter emissions at this time.

REFERENCES

1. Racette, D. J. and H. D. Griffin. 1977. Snow sampling study, Red Rock, February, 1977. Ontario Ministry of the Environment.
2. Griffin, H. D. and D. J. Racette. 1978. Moss bag exposure (1977) and snow sampling studies (1978) in the vicinity of Domtar Packaging Limited, Red Rock. Ontario Ministry of the Environment.
3. Racette, D. J. and H. D. Griffin. 1986. Moss exposure surveys in the vicinity of Domtar Packaging, Red Rock, 1983 and 1984. Ontario Ministry of the Environment.
4. Ontario Ministry of the Environment. 1981. Outlines of analytical methods, Laboratory Services Branch.
5. Griffin, H. D. 1986. Air quality, northwestern Ontario. Annual report, 1985. Ontario Ministry of the Environment.




Figure 1. Snow sampling sites, Red Rock, 1986.




Figure 2. Levels of suspended solids (mg/l) in meltwater from snow collected in the vicinity of Domtar Packaging Limited, Red Rock, February 8, 1986.

TABLE 1. Levels of calcium, sodium, chloride, sulphate (mg/l) and pH in meltwater from snow collected in the vicinity of Domtar Packaging Limited, Red Rock, February 8, 1978 and February 14, 1986.

Site	Calcium		Sodium		Chloride		Sulphate		pH	
	1978	1986	1978	1986	1978	1986	1978	1986	1978	1986
1	2	5	1	2	<1	<1	4	5	9.0	8.2
4	5	10	5	7	<1	1	14	7	9.5	10.0
6		7		12		<1		10		9.8
7	84	38	35	45	32	4	74	62	11.4	9.9
8	6	5		3	1	<1	10	4	6.6	7.6
11 ^a	4	4	4	3	3	<1	9	4	8.6	8.6
14 ^a	3	4	2	2	1	2	6	3		8.5
16	8	8	6	6	4	2	13	9	10.0	9.7
17 ^a		6		4		2		6		9.5
18 ^a	2	3	<1	1	<1	<1	3	2	8.8	7.5
25 ^a	3	3	5	1	1	<1	12	2	8.6	7.7
Controls	<1	<1	<1	1	<1	2	<1	<1	5.0	4.9
Guidelines	2		2		4		3			

^aSites off mill property.

TABLE 2. Levels of carbon, solids (mg/l) and conductivity (μ mhos/cm) in meltwater from snow collected in the vicinity of Domtar Packaging Limited, Red Rock, February 14, 1986.

Site	Carbon			Solids			Conductivity
	Dissolved inorganic	Dissolved organic	Total particulate	Dissolved	Suspended	Total	
1	3	1	63	24	11	35	40
4	6	3	29	56	160	210	98
6	7	6	550	67	79	150	99
7	23		66	370	1300	1700	300
8	4	10	23	35	180	220	38
11 ^a	3	3	3	27	52	79	37
14 ^a	2	2	1	18	10	28	34
16	4	3					73
17 ^a	3	2	8	34	18	52	54
18 ^a	1	<1	4	11	5	16	25
25 ^a	2	1	4	13	8	21	77
Controls	0	<1	2	3	2	5	15
Guidelines					30		60

^aSites off mill property.

DISTRIBUTION LIST

Report on: Snow sampling survey in the vicinity of Domtar
Packaging, Red Rock, 1986.

Northwestern Region: Director
Manager, Industrial Abatement; District
Officer; Manager, Technical Support;
Regional Laboratory: Water Quality
Supervisor; Trace Contaminant Supervisor

Northeastern Region: Chief, Air Quality Assessment

Waste management Branch: Manager, Waste Management Policy Section

Laboratory Services Branch: Director
Supervisor, Vegetation & Soils Unit

Air Resources Branch: Director
Manager, Phytotoxicology Section

Environmental Approvals and
Land Use Planning Branch: Supervisor, Approvals Engineering

Communications Branch: Jan Fairweather (10 copies)
Gerry Rego (20 copies)

Ministry of Labour: Supervisor, Industrial Health and
Safety Branch

Thunder Bay District Health Unit: Medical Officer of Health

Domtar Packaging: Technical Services Superintendent
(Mr. D. R. McNinch)

Township of Red Rock: Clerk-Treasurer (B. Holms)

Nipigon Gazette: Editor



96936000009239